



REPÚBLICA BOLIVARIANA DE VENEZUELA
 INSTITUTO NACIONAL DE AERONÁUTICA CIVIL
 SERVICIO A LA NAVEGACIÓN AÉREA
 COORDINACIÓN DE INFORMACIÓN AERONÁUTICA
 TEL: (58)212 3551325. FAX: (58) 3551325.
 AFTN: SVMYIYOYX/SVMYINYX/SVMYIYNYN.
 E-mail: ais@inac.gob.ve
notam.maiquetia@inac.gob.ve

**SUMMARY
NOTAM**

**A004/11
MAY 01st, 2011**



SUMMARY NOTAM IN FORCE

NR. NOTAM	LOCATION	TEXT
-----------	----------	------

YEAR 2010

A0326/10 BARQUISIMETO (SVBM)
 EFFECTIVE FROM 10/04/20 AND PERMANENT AMENDMENT AMENDMENT VENEZUELA/AIP PART 2.4-1 SVBM AD 2.3 HOURS OPERATIONS ITEM 8 WHERE SAY:MON-FRI,SAT,SUN,HOL:1000/0100UTC,READ AS:MON-FRI,SAT,SUN,HOL:1030/0230UTC, ITEM 12 WHERE SAY: OTHER HR PPR 30MINUTE BEFORE 0251-4423667, READ AS:OTHER HOURS PPR 30MINUTE BEFORE 0251-4425590.

C0674/10

A0587/10 MARACAIBO (SVMC)
 EFFECTIVE FROM 10/06/28 UNTILL 11/06/30 DAILY 1130/2310 CAUTION OPERATIONS TKOF/LDG/TAX DUE WORK CUTTING GRASS ON MOVEMENT AREA. MEN AND EQUIPMENT IN THE ZONE.

C1195/10

A1037/10 FIR MAIQUETIA (SVZM)
 EFFECTIVE FROM 10/11/11 UNTILL 11/09/22 RNAV 5 IMPLEMENTATION WITHIN FIR/MAIQUETIA AREA SUSPEND UNTILL 22SEP2011.

C2096/10

A1156/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 DAILY 1200/2200 CAUTION OPERATIONS TAKEOFF/LANDING DUE CUTTING GRASS WORK IN PROGRESS ON SECURITY ZONE RUNWAY 10/28 AND 09/27.MEN AND EQUIPMENT IN THE ZONE.

C2316/10

A1157/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 IS SUSPENDED AIRCRAFT PARKING ON AUXILIARY TERMINAL. CAUTION OPERATIONS TAX.

C2317/10

A1158/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTIL 11/06/30 DISPLACE THRESHOLD 28 500M DUE WORK IN PROGRESS, LENGTH RUNWAY 10/28 AVAILABLE 3000M, DECLARED DISTANCE (M):

RUNWAY TORA TODA ASDA LDA

10 3000 3000 3000 3000

28 3000 3000 3000 3000 .CAUTION. MEN AND EQUIPMENT IN THE ZONE.

C2319/10

A1159/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 DAILY 1200/2200 WILL TAKE PLACE ACTIVITY DISPERSION OF BIRD WITH FIREWORKS OVER ADJACENT OF AIR SPACE SVMI/AIRPORT. PREVIOUS ATS AND AIRPORT AUTHORITIES COORDINATION.CAUTION.

C2320/10

A1160/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 DAILY 1200/2200 CAUTION TKOF/LDG/TAX OPERATIONS DUE WORK SECURITY ZONE SIDE SOUTH RUNWAY 10/28 BETWEEN TAXIWAY A,B,C,D,E,F.MEN AND EQUIPMENT IN THE ZONE.

C2321/10

A1161/10 MAIQUETIA (SVMI)
 EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 TAXIWAY F CLOSED BETWEEN TAXIWAY D AND E DUE RAISING AND SINKING ASPHALT LAYER.

C2322/10



SUMMARY NOTAM IN FORCE

A1162/10 MAIQUETIA (SVMI)
EFFECTIVE FROM 10/12/13 UNTILL 11/06/30 IS RESTRICTED OPERATIONS TKOF RUNWAY 09/27 UNTILL MAXIMUM WEIGHT 20.000 KG. CAUTION.
C2323/10

A1163/10 MAIQUETIA (SVMI)
EFFECTIVE FROM 10/12/14 UNTILL 11/06/30 DAILY 2230/1030 IS SUSPENDED OPERATIONS TKOF RUNWAY 09 DUE LIGHT OUT OF SERVICE.
C2324/10

A1164/10 BARCELONA (SVBC)
EFFECTIVE FROM 10/12/14 AND PERMANET INSERT IN VENEZUELA AIP PART AD 2.2-15 INSTRUMENT APPROACH CHART BARCELONA ILS DME RUNWAY 15 OF DATE 23SEP10, AND AD 2.2-17 VOR RUNWAY 15 OF DATE 23SEP10, AS FOLLOWING: OPERATIONS BY CIRCUIT FOR RUNWAY 02, ONLY DIURNAL AND VISUAL METEOROLOGICAL CONDITION.
C2325/10

A1179/10 BARCELONA (SVBC)
EFFECTIVE FROM 10/12/20 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2.2-27 OF DATE 23SEP10, INSTRUMENT APPROACH CHART BARCELONA GRAL. JOSE ANTONIO ANZOATEGUI INTERNATIONAL RNAV (GNSS) RUNWAY 20 AS FLW: DIST BETWEEN CUM – (IAF) RAFAL: 28.38NM.-)
C2358/10

AÑO 2011

A0003/10 BARQUISIMETO (SVBM)
EFFECTIVE FROM 10/01/04 UNTILL 11/06/30 CAUTION TAX OPERATIONS DUE LIGHT TAXYWAY OUT OF SERVICE FROM C INTERSECTION UNTILL TAXYWAY RUNWAY 09.
C0004/11

A0004/10 BARQUISIMETO (SVBM)
EFFECTIVE FROM 10/01/04 UNTILL 11/06/30 SYSTEM OF LIGHTING APPROXIMATION RUNWAY 09 OUT OF SERVICE.
C0005/11

A0005/10 BARQUISIMETO (SVBM)
EFFECTIVE FROM 10/01/04 UNTILL 11/06/30 CAUTION TAX OPERATIONS DUE EXISTENCE HOLE ON AIXS OF THE TAXYWAY LOC S RESERVOIR NR 1. DIMENSIONS APRX LEN 35CM X WD 20CM X DPT 10CM.-)
C0006/11

A0013/10 MAIQUETIA (SVMI)
EFFECTIVE FROM 10/01/10 UNTILL 11/06/30 CAUTION OPERATIONS TAX APRON INTERSECTION INTERNATIONAL DUE DEFORMATION LAYER ASPH.
C0026/11

A0019/10 BARQUISIMETO (SVBM)
EFFECTIVE FROM 10/01/11 UNTILL 11/06/30 POSITION PARKING 3 ON COMMERCIAL AVIATION CLOSED DUE HOLE AND FAILURE FLAGSTONE.
C0036/11

A0021/10 BARQUISIMETO (SVBM)
EFFECTIVE FROM 10/01/11 UNTILL 11/06/30 CAUTION OPERATIONS TAX DUE FRACTURED SLABS ON APRON AVIATION GENERAL LOC ADJACENT POSITION PARKING 3C.
C0038/11

A0100/11 JOSEFA CAMEJO (SVJC)
EFFECTIVE FROM 11/02/14 UNTILL 11/06/28 DAILY 1230/2130 CAUTION OPERATIONS TKOF/LDG SECURITY ZONE RUNWAY 09/27 DUE WORK DRANAGE CHANNEL.MEN AND EQUIPMENT IN THE ZONE.-
C0202/11



SUMMARY NOTAM IN FORCE

- A0112/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/02/14 UNTILL 11/05/15 APP FREQUENCY 121.1MHZ OUT OF SERVICE, OPERATE ON FREQUENCY 119.1MHZ.CAUTION.
C0227/11
- A0118/11 VALENCIA (SVVA)**
EFFECTIVE FROM 11/02/17 UNTILL 11/07/20 HAS BEEN INSTALLATION EQUIPMENT VOR/DME PORTABLE WITH FOLLOWING CHARACTERISTICS: ID: VAL FREQUENCY: 108.2MHZ CH-19X COORDENATED: 100853.3N/0675514.2W.
C0248/11
- A0120/11 GUANARE (SVGU)**
EFFECTIVE FROM 11/02/17 UNTILL 11/05/30 NDB GRE 318 KHZ OUT OF SERVICE.
C0250/11
- A0123/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/02/18 UNTILL 11/05/25 TWR 118.7 MHZ OUT OF SERVICE. OPERATE IN FREQUENCY 121.7 MHZ. CAUTION.
C0255/11
- A0124/11 SAN TOME (SVST)**
EFFECTIVE FROM 11/02/18 UNTILL 11/05/25 DME CH112X OUT OF SERVICE.
C0258/11
- A0158/11 MARGARITA (SVMG)**
EFFECTIVE FROM 11/03/02 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.23-15 OF DATE 23SEP10, INSTRUMENT APPROACH CHART (IAC) MARGARITA INTL DEL CARIBE GRAL. SANTIAGO MARINO VOR/DME RUNWAY 09. MISSED APPROACH WHERE SAYS : CLIMBING TO 1500FT MUST SAY: CLIMBING TO 2500FT.
C0340/11
- A0161/11 MARGARITA (SVMG)**
EFFECTIVE FROM 11/03/02 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.23-18 OF DATE 23SEP10, STANDARD INSTRUMENT DEPARTURE (SID) RUNWAY 09, MARGARITA INTL DEL CARIBE GRAL. SANTIAGO MARINO. LEGEND SALIDA SARNI UNO: WHERE SAYS : A PSN SIRAS MUST SAY: A PSN SARNI
C0343/11
- A0168/11 MAIQUETIA (SVMIO)**
EFFECTIVE FROM 11/03/03 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.24-26 OF DATE 23SEP10, STANDARD INSTRUMENT DEPARTURE (SID) RWY 09, RWY 10, MAIQUETIA INTL SIMON BOLIVAR, OSMAR DEPARTURE: WHERE SAYS: TURN RIGHT MUST SAY: TURN LEFT.
C0354/11
- A0170/11 VALENCIA (SVVA)**
EFFECTIVE FROM 10/10/25 UNTILL 11/07/05 DVOR VAL FREQUENCY 117.4 MHZ OUT OF SERVICE DUE MAINTENANCE.
C0360/11
- A0182/11 VALENCIA (SVVA)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 LANDING SYSTEM IVAL FREQUENCY 110.3 MHZ OUT OF SERVICE.
C0386/11
- A0183/11 VALENCIA (SVVA)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 APPLICATION OF INSTRUMENTS APPROACH CHART VALENCIA ARTURO MICHELENA/INTERNATIONAL ILS/DME RUNWAY 10 SVVA IAC/2 OF DATE 23SEP10 IS SUSPENDED.
C0387/11



SUMMARY NOTAM IN FORCE

- A0184/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 10/12/09 UNTILL 11/08/08 NDB MIQ 292 KHZ OUT OF SERVICE.
C0390/11
- A0185/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 IS SUSPENDED APPLICATION INSTRUMENT APPROACH CHART MAIQUETIA INTERNATIONAL SIMON BOLIVAR NDB-C SVMI IAC/6 DATE 23SEP10.-
C0391/11
- A0186/11 FIR MAIQUETIA (SVZM)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 IS SUSPENDED ATC SERVICE ON ROUTE UL216 BETWEEN POSITION ZORRO-VOR/PAY DUE FAILURE COMMUNICATION VHF GROUND / AIR FREQUENCY 127.95MHZ.
C0392/11
- A0187/11 BARQUISIMETO (SVBM)**
EFFECTIVE FROM 11/03/09 AND PERMANENT AMENDMENT VENEZUELA/AIP AD 2.5 AIP SUPPLEMENT A03/11 OF DATE 10FEB11 STANDARD INSTRUMENT DEPARTURE (SID) RUNWAY 27 BARQUISIMETO INTL JACINTO LARA COORD PSN KOKRY WHERE SAYS: 101351N 694136W MUST SAY: 101423N 694101W.
C0397/11
- A0197/11 PTO.ORDAZ (SVPR)**
EFFECTIVE FROM 10/12/16 UNTILL 11/08/15 INTERSECTION C CLOSED DUE RISEL LAYER ASPHALT.
C0410/11
- A0198/11 SAN FELIPE (SVSP)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 NDB SPE 230KHZ OUT OF SERVICE.
C0411/11
- A0199/11 CALABOZO (SVCL)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 VOR/DME CZO 116.3 MHZ CH110X OUT OF SERVICE.
C0414/11
- A0200/11 CARUPANO (SVCP)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 NDB CUP 270KHZ OUT OF SERVICE.
C0415/11
- A0201/11 MARACAIBO (SVMC)**
EFFECTIVE FROM 10/12/22 UNTILL 11/08/15 RADAR PRIMARY OUT OF SERVICE..
C0416/11
- A0208/11 CALABOZO (SVCL)**
EFFECTIVE FROM 10/11/04 UNTILL 11/08/25 NDB CZO FREQUENCY 215 KHZ OUT OF SERVICE.
C0430/11
- A0215/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 11/03/04 AND PERMANENT TAXIWAY J CLOSED BETWEEN TAXIWAY K AND L DUE PARKING AIRCRAFT IN THE ZONE.
C0442/11
- A0224/11 VALENCIA (SVVA)**
EFFECTIVE FROM 11/03/15 AND PERMANENT ADMENDMENT VENEZUELA AIP PAGES ENR 4.1-9,ENR 6.1,ENRC 1N,ENRC 2N,TMA MAIQUETIA,AD 2.37-9, AD 2.37-13, AD2.37-21, AD 2.37-23, AD 2.37-25 OF DATE 23SEP10.WHERE SAYS:VOR/DME VAL FREQUENCY 117.4MHZ CH-121X COORDENATE: 100852.3N675521.9W, MOST SAY:VOR/DME VAL FREQUENCY 108.2MHZ CH-19X COORDENATE:100853.3N675514.2W.
C0457/11



SUMMARY NOTAM IN FORCE

A0225/11 BARCELONA (SVBC)

EFFECTIVE FROM 10/11/03 UNTILL 11/08/30 MILITARY OPERATIONS WILL TAKE PLACE WITHIN FOLOWING ZONE:

ZONE A1: RADIAL 203/266 BETWEEN 10/40NM VOR BNA

ZONE A2: RADIAL 140/160 BETWEEN 20/80NM VOR BNA

ZONE A3: RADIAL 077/110 BETWEEN 10/40NM VOR BNA. VFR FLIGHT WITHIN THAT ZONE IS SUSPENDED. REMAIN CONTACT PERMANENT WITH APP/BARCELONA ON FREQUENCY 121.1MHZ.PREVIOUS ATS CIV/MIL AND AIRPORT AUTHORITIES COORDINATION. CAUTION. FL100/FL400

C0459/11

A0226/11 CABO CODERA (SVXX)

EFFECTIVE FROM 10/11/08 UNTILL 11/08/30 CBC VOR/DME 113.5 MHZ CH82X OUT OF SERVICE

C0463/11

A0227/11 MARGARITA (SVMG)

EFFECTIVE FROM 10/11/08 UNTILL 11/08/30 TWR/SVMG OPERATE FROM TORRE AUXILIARY ILIARY LOCATED AT NORTHWEST APRON COMMERCIAL OPERATE ONLY FREQUENCY 118.6MHZ DUE WORK.CAUTION.

C0464/11

A0229/11 HIGUEROTE (SVHG)

EFFECTIVE FROM 10/11/05 UNTILL 11/09/10 HOT NDB FREQUENCY 353KHZ OUT OF SERVICE..

C0475/11

A0230/11 CARORA (SVCO)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 COR VOR/DME 112.7MHZ CH74X OUT OF SERVICE DUE MAINTENANCE.

C0477/11

A0231/11 YARITAGUA (SVXX)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 NDB YAR FREQUENCY 260KHZ OUT OF SERVICE.

C0478/11

A0232/11 MENE MAUROA (SVXX)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 DME CH126X OUT OF SERVICE.

C0479/11

A0233/11 TUCUPITA (SVTC)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 NDB TUC 225 KHZ OUT OF SERVICE.

C0480/11

A0242/11 PTO.AYACUCHO (SVPA)

EFFECTIVE FROM 10/11/05 UNTILL 11/09/20 VOR PAY FREQUENCY 116.4 MHZ OUT OF SERVICE DUE MAINTENANCE

C0496/11

A0245/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 EFFECTIVE FROM 10/12/09 UNTILL 11/03/30 CAUTION TKOF/LDG/TAX OPERATIONS RUNWAY 09 DUE CONC LIFTING EDGE RUNWAY APROXIMATE 300METER OF THRESHOLD 09.

C0513/11

A0246/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 TAX OPERATIONS APRON DUE CONC FLAGSTONE DRAINAGE.

C0514/11

A0247/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 CAUTION OPERATIONS TAX DUE SINKING E AND CENTRAL OUT OF SERVICE.

C0515/11



SUMMARY NOTAM IN FORCE

- A0258/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION OPERATIONS TKOF/LDG/TAX DUE HOLE RUNWAY 33 FOLLOWING CHARACTERISTICS 27CM WIDE X 40CM LEN X 5CM DEPTH LOCATED 440M THRESHOLD.
C0550/11
- A0260/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION TAX OPERATIONS TAXIWAY B FRONT OF TWR DUE CRACKS ASPHALT LAYER.
C0552/11
- A0261/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 RESTRICTED OPERATIONS TAX IN TAXIWAY LOCATED BETWEEN RUNWAY 15/33 AND APRON SOUTH AIRCRAFT MAXIMUN WEIGHT UNTILL 192000 POUND.
C0553/11
- A0262/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTIL 11/10/15 DISPLACED THRESHOLD 33 240M DUE WORK LEN AVAILABLE RUNWAY 15/33 2760M. DECLARED DISTANCE(M):
RUNWAY TORA TODA ASDA LDA
15 2760 2760 2760 2760
33 2760 2760 2760 2760
CAUTION MEN AND EQUIPMENTS IN THE ZONE
C0554/11
- A0263/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION OPERATIONS TKOF/LDG/TAX DUE HOLE RUNWAY 15 FOLLOWING CHARACTERISTICS 46CM WIDE X 80CM LEN X 7CM DEPTH LOCATED 60M INTERSECTION CENTRAL.
C0555/11
- A0264/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 RUNWAY 02/20 CLOSED DUE WORK ASPHALT. MEN AND EQUIPMENT IN THE ZONE.
C0556/11
- A0282/11 SAN ANTONIO (SVSA)**
EFFECTIVE FROM 09/03/02 AND PERMANENT MET ANTENNA INSTALLATION HEIGHT 11M, LOCATED: SECURITY ZONE RIGHT RUNWAY 17 AT 800M THRESHOLD AN 105M RUNWAY CENTER LINE. CAUTION.
C0607/11
- A0283/11 STA.BARBARA DEL ZULIA(SVSZ)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 STB VOR FREQUENCY 114.9 MHZ OPERATE ON TEST, DO NOT USE.
C0608/11
- A0284/11 STA.BARBARA DEL ZULIA(SVSZ)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 DME CH96X OUT OF SERVICE
C0609/11
- A0285/11 LOS ROQUES (SVLR)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 VOR/DME LRS FREQUENCY 113.1MHZ CH78X OUT OF SERVICE.
C0611/11
- A0289/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 11/04/05 UNTILL 11/06/30 EVRY TUESDAY BETWEEN 1230/1830 CAUTION TKOF/LDG/TAX OPERATIONS MOVEMENT AEREA AIRPORT/SVMI DUE PARTIAL EXERCICE OF EMERGENCY. MEN AND EQUIPMENT ON THE ZONE.
C0618/11.



SUMMARY NOTAM IN FORCE

- A0292/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/04/05 UNTILL 11/0630 POSITION PARKING CARGO RAMP NR 02 CLOSED DUE CRACKING ASPHALT LYR. CAUTION.
C0621/11
- A0293/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/04/05 UNTILL 11/06/30 CAUTION OPERATIONS TAX NIGHT DUE LIGHTS INTERCEPTION E OUT OF SERVICE.
C0622/11
- A0295/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/04/05 UNTILL 11/06/30 CAUTION OPERATIONS TAS TAXIWAY J BETWEEN TAXIWAY L AND M DUE CRACKING LYR ASPHALT.
C0624/11
- A0296/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/04/05 UNTILL 11/06/30 CAUTION LANDING OPERATIONS FOR AIRCRAFT IN FIRST THIRD THRESHOLD 10 APPROXIMATE AT 250METER DUE CRACK ON CONCRET, TO USE REFERENCE POUNT SIGNAL.
C0625/11
- A0297/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/04/05 UNTILL 11/06/30 CAUTION TAX OPERATIONS CARGO ZONE POSITION PARKING NR 3 DUE RESISTANCE ASPHALT LYR UNTILL MAXIMUM WEIGHT 70.000KG.
C0626/11
- A0300/11 MAIQUETIA (SVM)**
EFFECTIVE FROM 11/03/31 UNTILL 11/05/06 ACC/MAIQUETIA SECTOR 4 FREQUENCY 126.0MHZ LIMITED DUE FAILURE. CAUTION.
C0631/11
- A0312/11 BARQUISIMETO (SVBM)**
EFFECTIVE FROM 11/04/08 UNTILL 11/05/15 APP/BARQUISIMETO OPERATE FREQUENCY 120.7MHZ DUE FAILURE FREQUENCY 119.4 MHZ.CAUTION.
C0650/11
- A0324/11 MARGARITA (SVMG)**
EFFECTIVE FROM 11/04/08 UNTILL 11/12/31 DAILY 1130/2230 CAUTION OPERATIONS TKOF/LDG DUE CUTTING GRASS WORK ON SECURITY ZONE RUNWAY 09/27 AND TAXIWAY. MEN AND EQUIPMENT IN THE ZONE.
C0670/11
- A0330/11 VALENCIA (SVVA)**
EFFECTIVE FROM 11/03/15 UNTILL 11/05/16 DAILY 1200/2130 CAUTION OPERATIONS TKOF/LDG/TAX DUE CUTTING GRASS WORK SECURITY ZONE RUNWAY 10/28 AND TAXIWAY. MEN AND EQUIPMENT IN THE ZONE.
C0679/11
- A0333/11 STO.DOMINGO (SVSO)**
EFFECTIVE FROM 11/04/08 UNTILL 11/05/13 ENERGY AUXILIARY AIRPORT OUT OF SERVICE DUE MAINTENANCE.CAUTION.
C0683/11
- A0334/11 STO.DOMINGO (SVSO)**
EFFECTIVE FROM 11/04/13 UNTILL 11/05/13 DAILY 1043/2257 AIRPORT/SVSO OPERATE SUNRISE TO SUNSET.
C0684/11



SUMMARY NOTAM IN FORCE

A0338/11 FIR MAIQUETIA (SVZM)

EFFECTIVE FROM 10/11/11 UNTILL 11/08/15 THE SECTIONS OF ROUTE RNAV UL793 BETWEEN AKNOV-SIMUR AND UM656 ACTIVATE BETWEEN ESPIM-LOKES BEING APPLIED THE FLW SEPARATION: 1)ROUTE UL793, SENSE OF FLIGHT FIR SBAZ/FIR SVZM,FL280,FL320,FL360, FL400 MADE LEVEL IN AKNOV. 2)ROUTE UL793, SENSE OF FLIGHT FIR SVZM/FIR SBAZ,FL250,FL270,FL290, FL310,FL330,FL350,FL390,FL410,FL450,MADE LEVEL IN SIMUR.3)ROUTE UM656 SENSE ONLY FIR SBAZ/FIR SVZM,FL260,FL300,FL340,FL380 FL430 MADE LEVEL IN ESPIM.4)NOT AUTHORIZED CHANGES OF FLIGHT IN SECTIONS UM656 BETWEEN LOKES-ESPIM, UL793 BETWEEN AKNOV-SIMUR.5)THE LONGITUDINAL SEPARATION IN ROUTE UL793-UM656 FOR SAME AIRCRAFT ROUTE AND FL ARE 15MIN BEFOR POSITION SIMUR,AKNOV-ESPIM RESPECTIVELY.

C0694/11

A0352/11 MARGARITA (SVMG)

EFFECTIVE FROM 11/04/20 UNTILL 11/07/20 APPROACH LIGHTING SYSTEM RUNWAY 09 OUT OF SERVICE.

C0723/11

A0361/11 BARCELONA (SVBC)

EFFECTIVE FROM 11/04/27 UNTILL 11/05/02 FUEL SERVICE AVGAS 100/130 OCTANES NOT AVAILABLE

C0744/11

A0368/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/04/28 UNTILL 11/05/02 DAILY 1730/2030 CAUTION TAX OPERATIONS DUE WORK MAINTENANCE COMMERCIAL APRON. MEN AND EQUIPMENT IN THE ZONE.

C0757/11

A0369/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 10/10/25 UNTILL 11/10/28 DAILY 1230/2030 CAUTION OPERATIONS TKOF/LDG/TAX DUE WORK CUTTING GRASS MOVEMENT AREA RUNWAY 09/27 TAXIWAY AND APRON . MEN AND EQUIPMENT IN THE ZONE

C0758/11

A0370/11 MARGARITA (SVMG)

EFFECTIVE FROM 11/04/29 UNTILL 11/05/28 APRIL 29/MAY 01 1630/2230, MAY 06/07,13/14,20/21,27/28 1630/2230 IS RESTRICTED AVIATION GENERAL APRON DUE OPERATIONS MIL.CAUTION TAX OPERATIONS.

C0761/11

A0375/11 LA ORCHILA (SVLO)

EFFECTIVE FROM 11/05/02 UNTILL 11/05/20 DAILY 1130/2130 EXERCICE FIRING AND AIR LAUNCHING WILL TAKE PLACE WI FLW COORD: 112144N/0663704W,121836N/0663547W,122516N/0662620W,122932N/0661218W 122745N/0655434W,121714N/0653748W,120014N/0652807W,114249N/0652716W,112919N/0653217W,12024N/0653928W, 112144N/0663704W AND ZONE SVP2521, AIRWAY AFFECTED: A551 FROM MARPI/MASPA, A550 FROM FAROS/HENRY, A563 FROM LRS/KOMPU, W44 FROM VARGA/TOROP, W30 FROM DOSRA/KOMPU, W45 FROM LRS/VARGA, G432 FROM IRIBE/LRS. REMAIN CONTACT PERMANENT APP/MAIQUETIA FREQUENCY 120.1MHZ AND ACC/MAIQUETIA SECT 2 FREQUENCY 125.2MHZ. PREVIOUS ATS MIL COORDINATION.CAUTION.FL005/FL180.

C0773/11

A0376/11 VALENCIA (SVVA)

EFFECTIVE FROM 11/04/29 UNTILL 11/05/15 CAUTION OPERATIONS TKOF/LDG DUE PRESENCE 2 HOLES APROXIMATE AT 8METER RUNWAY 10 EDGE NORTH WITH FOLLOWING CHARACTERISTICS:

- 1) LONGITUD 70 X 30CM WIDE X 4CM DEPT
- 2)LONGITUD 45 X 25CM WIDE X 4CM DEPT.

A0376/11



REPÚBLICA BOLIVARIANA DE VENEZUELA
INSTITUTO NACIONAL DE AERONÁUTICA CIVIL
SERVICIO A LA NAVEGACIÓN AÉREA
COORDINACIÓN DE INFORMACIÓN AERONÁUTICA
TEL: (58)212 3551325. FAX: (58) 3551325.
AFTN: SVMY0YX/SVMYNYX/SVMYNYN.
E-mail: ais@inac.gob.ve
notam.maiquetia@inac.gob.ve

**SUMMARY
NOTAM**

**A004/11
MAY 01st, 2011**

SUMMARY NOTAM IN FORCE

LAST PUBLICATIONS

AMDT/AIRAC AIP/VENEZUELA: 4FH EDITION VENEZUELA/AIP 23SEP2010

AMDT REG AIP/VENEZUELA: NIL

SUP AIRAC/AIP: A01,A02,A03/11

AIC: A01/11

ELABORADO POR: GJF 01/05/11.-

NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR REPLACED OR INCORPORATED TO AIP BY MEANS AMDT