



REPÚBLICA BOLIVARIANA DE VENEZUELA
 INSTITUTO NACIONAL DE AERONÁUTICA CIVIL
 SERVICIO A LA NAVEGACIÓN AÉREA
 COORDINACIÓN DE INFORMACIÓN AERONÁUTICA
 TEL: (58)212 3551325. FAX: (58) 3551325.
 AFTN: SVMYIYX/SVMYINYX/SVMYIYN.
 E-mail: ais@inac.gob.ve
notam.maiquetia@inac.gob.ve

**SUMMARY
 NOTAM**

**A006/11
 JUL 01st, 2011**



SUMMARY NOTAM IN FORCE

NR. NOTAM	LOCATION	TEXT
-----------	----------	------

YEAR 2010

A0326/10 BARQUISIMETO (SVBM)
 EFFECTIVE FROM 10/04/20 AND PERMANENT AMENDMENT AMENDMENT VENEZUELA/AIP PART 2.4-1 SVBM AD 2.3 HOURS OPERATIONS ITEM 8 WHERE SAY: MON-FRI, SAT, SUN, HOL: 1000/0100UTC, READ AS: MON-FRI, SAT, SUN, HOL: 1030/0230UTC, ITEM 12 WHERE SAY: OTHER HR PPR 30MINUTE BEFORE 0251-4423667, READ AS: OTHER HOURS PPR 30MINUTE BEFORE 0251-4425590.
C0674/10

A1037/10 FIR MAIQUETIA (SVZM)
 EFFECTIVE FROM 10/11/11 UNTILL 11/09/22 RNAV 5 IMPLEMENTATION WITHIN FIR/MAIQUETIA AREA SUSPEND UNTILL 22SEP2011.
C2096/10

A1179/10 BARCELONA (SVBC)
 EFFECTIVE FROM 10/12/20 AND PERMANENT AMENDMENT AMENDMENT VENEZUELA/AIP PART AD 2.2-27 OF DATE 23SEP10, INSTRUMENT APPROACH CHART BARCELONA GRAL. JOSE ANTONIO ANZOATEGUI INTERNATIONAL RNAV (GNSS) RUNWAY 20 AS FLW: DIST BETWEEN CUM – (IAF) RAFAL: 28.38NM.-)
C2358/10

AÑO 2011

A0118/11 VALENCIA (SVVA)
 EFFECTIVE FROM 11/02/17 UNTILL 11/07/20 HAS BEEN INSTALLATION EQUIPMENT VOR/DME PORTABLE WITH FOLLOWING CHARACTERISTICS: ID: VAL FREQUENCY: 108.2MHZ CH-19X COORDENATED: 100853.3N/0675514.2W.
C0248/11

A0158/11 MARGARITA (SVMG)
 EFFECTIVE FROM 11/03/02 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.23-15 OF DATE 23SEP10, INSTRUMENT APPROACH CHART (IAC) MARGARITA INTL DEL CARIBE GRAL. SANTIAGO MARINO VOR/DME RUNWAY 09. MISSED APPROACH WHERE SAYS : CLIMBING TO 1500FT MUST SAY: CLIMBING TO 2500FT.
C0340/11

A0161/11 MARGARITA (SVMG)
 EFFECTIVE FROM 11/03/02 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.23-18 OF DATE 23SEP10, STANDARD INSTRUMENT DEPARTURE (SID) RUNWAY 09, MARGARITA INTL DEL CARIBE GRAL. SANTIAGO MARINO. LEGEND SALIDA SARNI UNO: WHERE SAYS : A PSN SIRAS MUST SAY: A PSN SARNI
C0343/11

A0168/11 MAIQUETIA (SVMY)
 EFFECTIVE FROM 11/03/03 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2, PAGE AD 2.24-26 OF DATE 23SEP10, STANDARD INSTRUMENT DEPARTURE (SID) RWY 09, RWY 10, MAIQUETIA INTL SIMON BOLIVAR, OSMAR DEPARTURE: WHERE SAYS: TURN RIGHT MUST SAY: TURN LEFT.
C0354/11

A0170/11 VALENCIA (SVVA)
 EFFECTIVE FROM 10/10/25 UNTILL 11/07/05 DVOR VAL FREQUENCY 117.4 MHZ OUT OF SERVICE DUE MAINTENANCE.
C0360/11

A0182/11 VALENCIA (SVVA)
 EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 LANDING SYSTEM IVAL FREQUENCY 110.3 MHZ OUT OF SERVICE.
C0386/11



SUMMARY NOTAM IN FORCE

- A0183/11 VALENCIA (SVVA)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 APPLICATION OF INSTRUMENTS APPROACH CHART VALENCIA ARTURO MICHELENA/INTERNATIONAL ILS/DME RUNWAY 10 SVVA IAC/2 OF DATE 23SEP10 IS SUSPENDED.
C0387/11
- A0184/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 10/12/09 UNTILL 11/08/08 NDB MIQ 292 KHZ OUT OF SERVICE.
C0390/11
- A0185/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 IS SUSPENDED APPLICATION INSTRUMENT APPROACH CHART MAIQUETIA INTERNATIONAL SIMON BOLIVAR NDB-C SVMI IAC/6 DATE 23SEP10.-
C0391/11
- A0186/11 FIR MAIQUETIA (SVZM)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/08 IS SUSPENDED ATC SERVICE ON ROUTE UL216 BETWEEN POSITION ZORRO-VOR/PAY DUE FAILURE COMMUNICATION VHF GROUND / AIR FREQUENCY 127.95MHZ.
C0392/11
- A0187/11 BARQUISIMETO (SVBM)**
EFFECTIVE FROM 11/03/09 AND PERMANENT AMENDMENT VENEZUELA/AIP AD 2.5 AIP SUPPLEMENT A03/11 OF DATE 10FEB11 STANDARD INSTRUMENT DEPARTURE (SID) RUNWAY 27 BARQUISIMETO INTL JACINTO LARA COORD PSN KOKRY WHERE SAYS: 101351N 694136W MUST SAY: 101423N 694101W.
C0397/11
- A0197/11 PTO.ORDAZ (SVPR)**
EFFECTIVE FROM 10/12/16 UNTILL 11/08/15 INTERSECTION C CLOSED DUE RISEL LAYER ASPHALT.
C0410/11
- A0198/11 SAN FELIPE (SVSP)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 NDB SPE 230KHZ OUT OF SERVICE.
C0411/11
- A0199/11 CALABOZO (SVCL)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 VOR/DME CZO 116.3 MHZ CH110X OUT OF SERVICE.
C0414/11
- A0200/11 CARUPANO (SVCP)**
EFFECTIVE FROM 10/11/02 UNTILL 11/08/15 NDB CUP 270KHZ OUT OF SERVICE.
C0415/11
- A0201/11 MARACAIBO (SVMC)**
EFFECTIVE FROM 10/12/22 UNTILL 11/08/15 RADAR PRIMARY OUT OF SERVICE..
C0416/11
- A0208/11 CALABOZO (SVCL)**
EFFECTIVE FROM 10/11/04 UNTILL 11/08/25 NDB CZO FREQUENCY 215 KHZ OUT OF SERVICE.
C0430/11
- A0224/11 VALENCIA (SVVA)**
EFFECTIVE FROM 11/03/15 AND PERMANENT ADMENDMENT VENEZUELA AIP PAGES ENR 4.1-9,ENR 6.1,ENRC 1N,ENRC 2N,TMA MAIQUETIA,AD 2.37-9, AD 2.37-13, AD2.37-21, AD 2.37-23, AD 2.37-25 OF DATE 23SEP10.WHERE SAYS:VOR/DME VAL FREQUENCY 117.4MHZ CH-121X COORDENATE: 100852.3N675521.9W, MOST SAY:VOR/DME VAL FREQUENCY 108.2MHZ CH-19X COORDENATE:100853.3N675514.2W.
C0457/11



SUMMARY NOTAM IN FORCE

A0225/11 BARCELONA (SVBC)

EFFECTIVE FROM 10/11/03 UNTILL 11/08/30 MILITARY OPERATIONS WILL TAKE PLACE WITHIN FOLOWING ZONE:

ZONE A1: RADIAL 203/266 BETWEEN 10/40NM VOR BNA

ZONE A2: RADIAL 140/160 BETWEEN 20/80NM VOR BNA

ZONE A3: RADIAL 077/110 BETWEEN 10/40NM VOR BNA. VFR FLIGHT WITHIN THAT ZONE IS SUSPENDED. REMAIN CONTACT PERMANENT WITH APP/BARCELONA ON FREQUENCY 121.1MHZ.PREVIOUS ATS CIV/MIL AND AIRPORT AUTHORITIES COORDINATION. CAUTION. FL100/FL400

C0459/11

A0226/11 CABO CODERA (SVXX)

EFFECTIVE FROM 10/11/08 UNTILL 11/08/30 CBC VOR/DME 113.5 MHZ CH82X OUT OF SERVICE

C0463/11

A0227/11 MARGARITA (SVMG)

EFFECTIVE FROM 10/11/08 UNTILL 11/08/30 TWR/SVMG OPERATE FROM TORRE AUXILIARY ILIARY LOCATED AT NORTHWEST APRON COMMERCIAL OPERATE ONLY FREQUENCY 118.6MHZ DUE WORK.CAUTION.

C0464/11

A0229/11 HIGUEROTE (SVHG)

EFFECTIVE FROM 10/11/05 UNTILL 11/09/10 HOT NDB FREQUENCY 353KHZ OUT OF SERVICE..

C0475/11

A0230/11 CARORA (SVCO)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 COR VOR/DME 112.7MHZ CH74X OUT OF SERVICE DUE MAINTENANCE.

C0477/11

A0231/11 YARITAGUA (SVXX)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 NDB YAR FREQUENCY 260KHZ OUT OF SERVICE.

C0478/11

A0233/11 TUCUPITA (SVTC)

EFFECTIVE FROM 10/11/08 UNTILL 11/09/10 NDB TUC 225 KHZ OUT OF SERVICE.

C0480/11

A0242/11 PTO.AYACUCHO (SVPA)

EFFECTIVE FROM 10/11/05 UNTILL 11/09/20 VOR PAY FREQUENCY 116.4 MHZ OUT OF SERVICE DUE MAINTENANCE

C0496/11

A0245/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 EFFECTIVE FROM 10/12/09 UNTILL 11/03/30 CAUTION TKOF/LDG/TAX OPERATIONS RUNWAY 09 DUE CONC LIFTING EDGE RUNWAY APROXIMATE 300METER OF THRESHOLD 09.

C0513/11

A0246/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 TAX OPERATIONS APRON DUE CONC FLAGSTONE DRANAGE.

C0514/11

A0247/11 JOSEFA CAMEJO (SVJC)

EFFECTIVE FROM 10/12/09 UNTILL 11/09/25 CAUTION OPERATIONS TAX DUE SINKING E AND CENTRAL OUT OF SERVICE.

C0515/11

A0258/11 BARCELONA (SVBC)

EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION OPERATIONS TKOF/LDG/TAX DUE HOLE RUNWAY 33 FOLLOWING CHARACTERISTICS 27CM WIDE X 40CM LEN X 5CM DEPTH LOCATED 440M THRESHOLD.

C0550/11



SUMMARY NOTAM IN FORCE

- A0260/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION TAX OPERATIONS TAXIWAY B FRONT OF TWR DUE CRACKS ASPHALT LAYER.
C0552/11
- A0261/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 RESTRICTED OPERATIONS TAX IN TAXIWAY LOCATED BETWEEN RUNWAY 15/33 AND APRON SOUTH AIRCRAFT MAXIMUM WEIGHT UNTILL 192000 POUND.
C0553/11
- A0262/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTIL 11/10/15 DISPLACED THRESHOLD 33 240M DUE WORK LEN AVAILABLE RUNWAY 15/33 2760M. DECLARED DISTANCE(M):
RUNWAY TORA TODA ASDA LDA
15 2760 2760 2760 2760
33 2760 2760 2760 2760
CAUTION MEN AND EQUIPMENTS IN THE ZONE
C0554/11
- A0263/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 CAUTION OPERATIONS TKOF/LDG/TAX DUE HOLE RUNWAY 15 FOLLOWING CHARACTERISTICS 46CM WIDE X 80CM LEN X 7CM DEPTH LOCATED 60M INTERSECTION CENTRAL.
C0555/11
- A0264/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/03/28 UNTILL 11/10/15 RUNWAY 02/20 CLOSED DUE WORK ASPHALT. MEN AND EQUIPMENT IN THE ZONE.
C0556/11
- A0282/11 SAN ANTONIO (SVSA)**
EFFECTIVE FROM 09/03/02 AND PERMANENT MET ANTENNA INSTALLATION HEIGHT 11M, LOCATED: SECURITY ZONE RIGHT RUNWAY 17 AT 800M THRESHOLD AN 105M RUNWAY CENTER LINE. CAUTION.
C0607/11
- A0283/11 STA.BARBARA DEL ZULIA(SVSZ)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 STB VOR FREQUENCY 114.9 MHZ OPERATE ON TEST, DO NOT USE.
C0608/11
- A0284/11 STA.BARBARA DEL ZULIA(SVSZ)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 DME CH96X OUT OF SERVICE
C0609/11
- A0285/11 LOS ROQUES (SVLR)**
EFFECTIVE FROM 10/12/03 UNTILL 11/07/15 VOR/DME LRS FREQUENCY 113.1MHZ CH78X OUT OF SERVICE.
C0611/11
- A0324/11 MARGARITA (SVMG)**
EFFECTIVE FROM 11/04/08 UNTILL 11/12/31 DAILY 1130/2230 CAUTION OPERATIONS TKOF/LDG DUE CUTTING GRASS WORK ON SECURITY ZONE RUNWAY 09/27 AND TAXIWAY. MEN AND EQUIPMENT IN THE ZONE.
C0670/11



SUMMARY NOTAM IN FORCE

A0338/11 FIR MAIQUETIA (SVZM)

EFFECTIVE FROM 10/11/11 UNTILL 11/08/15 THE SECTIONS OF ROUTE RNAV UL793 BETWEEN AKNOV-SIMUR AND UM656 ACTIVATE BETWEEN ESPIM-LOKES BEING APPLIED THE FLW SEPARATION: 1)ROUTE UL793, SENSE OF FLIGHT FIR SBAZ/FIR SVZM,FL280,FL320,FL360, FL400 MADE LEVEL IN AKNOV. 2)ROUTE UL793, SENSE OF FLIGHT FIR SVZM/FIR SBAZ,FL250,FL270,FL290, FL310,FL330,FL350,FL390,FL410,FL450,MADE LEVEL IN SIMUR.3)ROUTE UM656 SENSE ONLY FIR SBAZ/FIR SVZM,FL260,FL300,FL340,FL380 FL430 MADE LEVEL IN ESPIM.4)NOT AUTHORIZED CHANGES OF FLIGHT IN SECTIONS UM656 BETWEEN LOKES-ESPIM, UL793 BETWEEN AKNOV-SIMUR.5)THE LONGITUDINAL SEPARATION IN ROUTE UL793-UM656 FOR SAME AIRCRAFT ROUTE AND FL ARE 15MIN BEFOR POSITION SIMUR,AKNOV-ESPIM RESPECTIVELY.

C0694/11

A0352/11 MARGARITA (SVMG)

EFFECTIVE FROM 11/04/20 UNTILL 11/07/20 APPROACH LIGHTING SYSTEM RUNWAY 09 OUT OF SERVICE.

C0723/11

A0397/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/04/08 UNTILL 11/08/15 APP/BARQUISIMETO OPERATE FREQUENCY 120.7MHZ DUE FAILURE FREQUENCY 119.4 MHZ.CAUTION.

C0817/11

A0398/11 BARCELONA (SVBC)

EFFECTIVE FROM 11/02/14 UNTILL 11/08/15 APP FREQUENCY 121.1MHZ OUT OF SERVICE, OPERATE ON FREQUENCY 119.1MHZ.CAUTION.

C0819/11

A0422/11 BARCELONA (SVBC)

EFFECTIVE FROM 10/12/14 AND PERMANENT INSERT IN VENEZUELA AIP PART AD 2.2-15 INSTRUMENT APPROACH CHART BARCELONA ILS DME RUNWAY 15 OF DATE 23SEP10, AND AD 2.2-17 VOR RUNWAY 15 OF DATE 23SEP10, AS FOLLOWING: OPERATIONS BY CIRCUIT FOR RUNWAY 02 AND 33, ONLY DIURNAL AND VISUAL METEOROLOGICAL CONDITION.

C0864/11

A0424/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 10/10/25 UNTILL 12/05/12 MONDAY TO FRIDAY 1230/2030 CAUTION OPERATIONS TKOF/LDG/TAX DUE WORK CUTTING GRASS MOVEMENT AREA RUNWAY 09/27 TAXIWAY AND APRON . MEN AND EQUIPMENT IN THE ZONE

C0866/11.

A0446/11 B.A.LIBERTADOR (SVBL)

EFFECTIVE FROM 11/05/19 AND PERMANENT AMENDMENT VENEZUELA/AIP PART AD 2 PAGE AD 2.4-11 OF DATE 23SEP10, INSTRUMENT APPROACH CHART B.A.EL LIBERTADOR VOR/DME RUNWAY 09,VIEW PROFILE: WHERE SAY: 319 DEGRES,139 DEGRES MUST SAY: 274 DEGRES,094 DEGRES.

C0917/11

A0447/11 CIUDAD BOLIVAR (SVCB)

EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 CBL NDB 278KHZ OUT OF SERVICE.

C0919/11

A0448/11 GUIRIA (SVGI)

EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 GUI NDB 370KHZ OUT OF SERVICE.

C0920/11

A0450/11 TUMEREMO (SVTM)

EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 TMO NDB 215KHZ OUT OF SERVICE.

C0922/11



SUMMARY NOTAM IN FORCE

- A0451/11 UONQUEN (SVUQ)**
EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 KEM NDB 272KHZ OUT OF SERVICE.
C0923/11
- A0452/11 URIMAN (SVUM)**
EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 URM NDB 220KHZ OUT OF SERVICE.
C0924/11
- A0453/11 KANAVAYEN (SVKA)**
EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 KAV NDB 398KHZ OUT OF SERVICE.
C0925/11
- A0454/11 URICA (SVXX)**
EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 URC NDB 330KHZ OUT OF SERVICE.
C0926/11
- A0455/11 LOS PIJIGUAOS (SVXX)**
EFFECTIVE FROM 11/05/20 UNTILL 11/11/15 PIJ NDB 310KHZ OUT OF SERVICE.
C0927/11
- A0456/11 PUNTA SAN JUAN (SVXX)**
EFFECTIVE FROM 11/05/20 UNTIL 11/11/15 VSJ VOR/DME 112.9MHZ CH76X OUT OF SERVICE.
C0928/11
- A0462/11 GUANARE (SVGU)**
EFFECTIVE FROM 11/02/17 UNTILL 11/09/23 NDB GRE 318 KHZ OUT OF SERVICE.
C0939/11
- A0463/11 BARCELONA (SVBC)**
EFFECTIVE FROM 11/02/18 UNTILL 11/09/23 TWR 118.7 MHZ OUT OF SERVICE. OPERATE IN FREQUENCY 121.7
MHZ.CAUTION.
C0941/11
- A0464/11 SAN TOME (SVST)**
EFFECTIVE FROM 11/02/18 UNTILL 11/09/23 DME CH112X OUT OF SERVICE.
C0944/11
- A0481/11 MAIQUETIA (SVMI)**
EFFECTIVE FROM 11/05/30 AND PERMANENT EQUIPMENT ATIS OPERATE FREQUENCY 132.95MHZ
C0979/11
- A0520/11 B.A.LIBERTADOR (SVBL)**
EFFECTIVE FROM 11/05/18 UNTILL 11/08/18 DAILY 1231/2030 BAL VOR/DME FREQUENCY 113.9 MHZ CH86X OUT OF
SERVICE.
C1064/11
- A0522/11 VALENCIA (SVVA)**
EFFECTIVE FROM 11/03/15 UNTILL 11/07/16 DAILY 1200/2130 CAUTION OPERATIONS TKOF/LDG/TAX DUE CUTTING
GRASS WORK SECURITY ZONE RUNWAY 10/28 AND TAXIWAY. MEN AND EQUIPMENT IN THE ZONE.
C1068/11
- A0531/11 JOSEFA CAMEJO (SVJC)**
EFFECTIVA FROM 11/06/20 UNTILL 11/08/31 ATIS FREQUENCY 132.35 MHZ OUT OF SERVICE.
C1100/11



SUMMARY NOTAM IN FORCE

A0545/11 STO.DOMINGO (SVSO)

EFFECTIVE FROM 11/06/22 UNTILL 11/07/22 APPROACH LIGHTING SYSTEM RUNWAY 30 OUT OF SERVICE.
C1120/11

A0552/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/12/13 UNTILL 11/12/30 DAILY 1200/2200 CAUTION OPERATIONS TAKEOFF/LANDING DUE CUTTING GRASS WORK IN PROGRESS ON SECURITY ZONE RUNWAY 10/28 AND 09/27.MEN AND EQUIPMENT IN THE ZONE.

C1129/11

A0553/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/12/13 UNTILL 11/12/30 IS SUSPENDED AIRCRAFT PARKING ON AUXILIARY TERMINAL. CAUTION OPERATIONS TAX.

C1130/11

A0554/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/12/13 UNTILL 11/12/30 DISPLACE THRESHOLD 28 500M DUE WORK IN PROGRESS, LENGTH RUNWAY 10/28 AVAILABLE 3000M, DECLARED DISTANCE (M):

RUNWAY TORA TODA ASDA LDA

10 3000 3000 3000 3000

28 3000 3000 3000 3000 .CAUTION. MEN AND EQUIPMENT IN THE ZONE.

C1131/11

A0555/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/10/01 UNTILL 11/12/30 DAILY 1200/2200 WILL TAKE PLACE ACTIVITY DISPERSION OF BIRD WITH FIREWORKS OVER ADJACENT OF AIR SPACE SVMI/AIRPORT. PREVIOUS ATS AND AIRPORT AUTHORITIES COORDINATION.CAUTION.

C1132/11

A0557/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/12/13 UNTILL 11/12/30 IS RESTRICTED OPERATIONS TKOF RUNWAY 09/27 UNTILL MAXIMUM WEIGHT 20.000 KG. CAUTION.

C1134/11

A0558/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 10/12/14 UNTILL 11/12/30 DAILY 2230/1030 IS SUSPENDED OPERATIONS TKOF RUNWAY 09 DUE LIGHT OUT OF SERVICE.

C1135/11

A0559/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/01/10 UNTILL 11/12/30 CAUTION OPERATIONS TAX APRON INTERSECTION INTERNATIONAL DUE DEFORMATION LAYER ASPH.

C1136/11

A0560/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/03/04 UNTILL 11/12/30 TAXIWAY J CLOSED BETWEEN TAXIWAY K AND L DUE PARKING AIRCRAFT IN THE ZONE.

C1137/11

A0561/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/04/05 UNTILL 11/12/30 POSITION PARKING CARGO RAMP NR 02 CLOSED DUE CRACKING ASPHALT LYR. CAUTION.

C1138/11



SUMMARY NOTAM IN FORCE

A0562/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/04/05 UNTILL 11/12/30 CAUTION OPERATIONS TAS TAXIWAY J BETWEEN TAXIWAY L AND M DUE CRACKING LYR ASPHALT.
C1139/11

A0563/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/04/05 UNTILL 11/12/30 CAUTION LANDING OPERATIONS FOR AIRCRAFT IN FIRST THIRD THRESHOLD 10 APROXIMATE AT 250METER DUE CRACK ON CONCRET, TO USE REFERENCE POUNT SIGNAL.
C1140/11

A0564/11 MAIQUETIA (SVMI)

EFFECTIVE FROM 11/04/05 UNTILL 11/12/30 CAUTION TAX OPERATIONS CARGO ZONE POSITION PARKING NR 3 DUE RESISTANCE ASPHALT LYR UNTILL MAXIMUM WEIGHT 70.000KG.
C1141/11

A0580/11 BARQUISIMETO (SVBM)

JULY 02 03 09 10 16 17 23 24 BETWEEN 1021/2302 PARACHUTE JUMPING EXERCICE WILL TAKE PLACE OVER AIRPORT/SVBM WITHIN FOLLOWING COORDENATE: 100205N/0692100W. REMAIN CONTACT PERMANENT APP/BARQUISIMETO FREQUENCY 120.7MHZ. PREVIOUS ATS/MIL COORDINATION. CAUTION.SUPERFACE/FL080.
C1174/11

A0581/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/01/04 UNTILL 11/12/31 CAUTION TAX OPERATIONS DUE LIGHT TAXYWAY OUT OF SERVICE FROM C INTERSECTION UNTILL TAXYWAY RUNWAY 09.
C1176/11

A0582/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/01/04 UNTILL 11/12/31 SYSTEM OF LIGHTING APPROXIMATION RUNWAY 09 OUT OF SERVICE.
C1177/11

A0583/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/01/04 UNTILL 11/12/31 CAUTION TAX OPERATIONS DUE EXISTENCE HOLE ON AIXS OF THE TAXYWAY LOCATED S RESERVOIR NR 1. DIMENSIONS APROXIMATE LONGITUD 35CM X WIDE 20CM X DEPTH 10CM.
C1178/11

A0584/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/01/11 UNTILL 11/12/31 POSITION PARKING 3 ON COMMERCIAL AVIATION CLOSED DUE HOLE AND FAILURE FLAGSTONE.
C1179/11

A0585/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/01/11 UNTILL 11/12/31 CAUTION OPERATIONS TAX DUE FRACTURED SLABS ON APRON AVIATION GENERAL LOC ADJACENT POSITION PARKING 3C.
C1180/11

A0586/11 BARQUISIMETO (SVBM)

EFFECTIVE FROM 11/05/06 UNTILL 11/12/31 TWR SUPERFACE FREQUENCY 121.9 MHZ OUT OF SERVICE.
C1181/11

A0587/11 PTO.ORDAZ (SVPR)

EFFECTIVE FROM 11/06/28 AND PERMANENT HAS BEEN INSTALLATED EQUIPMENT DME WITH FOLLWING CHARACTERISTICS: CH:94X COORDENATE:081735.8N/0624510.8W REACH:120NM. INSERT IN VENEZUELA/AIP AD 2.29-7 PART SVPR AD 2.19, ENR 4.1-4.
C1182/11



REPÚBLICA BOLIVARIANA DE VENEZUELA
INSTITUTO NACIONAL DE AERONÁUTICA CIVIL
SERVICIO A LA NAVEGACIÓN AÉREA
COORDINACIÓN DE INFORMACIÓN AERONÁUTICA
TEL: (58)212 3551325. FAX: (58) 3551325.
AFTN: SVMYIYX/SVMYINYX/SVMYIYN.
E-mail: ais@inac.gob.ve
notam.maiquetia@inac.gob.ve

**SUMMARY
NOTAM**

**A006/11
JUL 01st, 2011**



SUMMARY NOTAM IN FORCE

A0588/11 PTO.ORDAZ (SVPR)
EFFECTIVE FROM 11/06/28 UNTILL 11/10/15 DME CH-94X OPERATE ON TEST. DO NOT USE.
C1183/11

A0589/11 FIR MAIQUETIA (SVZM)
JUNE 28 29 30 JULY 02 05 BETWEEN 1230/2330 WILL TAKE PLACE PRACTICE AND AIR DISPLAY OVER CARACAS METROPOLITAN AREA WITHIN FOLLOWING COORDENATED:103100N/0670400W, 102000N/0670400W, 103100N/0661500W, 101850N/0662200W,AFFECTED AIRWAY:A552 FROM CBC/ORODI, W27 FROM ORODI/TUY,W30 FROM TUY/CBC,W17 FROM MIQ/ALTOS,SVR2532,MEA FL190,IS SUSPENDE FLIGHT VFR-IFR WITHIN THAT ZONE.REMAIN CONTACT PERMANENT APP/TUY FREQUENCY 119.2MHZ AND ACC/MAIQUETIA SECTOR 1 FREQUENCY 128.5MHZ,SECTOR 2 FREQUENCY 125.2MHZ.PREVIOUS ATS MIL COORDINATION.CAUTION.-
SUPERFACE/FL180.
C1184/11

A0591/11 VALENCIA (SVVA)
EFFECTIVE FROM 11/06/29 UNTILL 11/07/02 DAILY 1230/2230 CAUTION TKOF/LDG OPERATIONS DUE WORK MAINTENANCE ZONE SOUTH RUNWAY 10/28. MEN AND EQUIPMENT IN THE ZONE.-
C1189/11

A0592/11 MAIQUETIA (SVMI)
JULY 02 BETWEEN 1230/1730 TAXIWAY F CLOSED BETWEEN TAXIWAY D AND E DUE WORK ASPHALT. MEN AND EQUIPMET IN THE ZONE. CAUTION.
A1197/11

A0595/11 MAIQUETIA (SVMI)
EFFECTIVE FROM 11/06/30 UNTILL 11/07/01 RUNWAY 09/27 CLOSED DUE ASPHALT WORK.CAUTION MEN AND EQUIPMENT IN THE ZONE.
C1200/11

LAST PUBLICATIONS
AMDT/AIRAC AIP/VENEZUELA: 4FH EDITION VENEZUELA/AIP 23SEP2010
AMDT REG AIP/VENEZUELA: NIL
SUP AIRAC/AIP: A01,A02,A03/11
AIC: A01/11
ELABORADO POR: GJF 01/07/11.-

NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR REPLACED OR INCORPORATED TO AIP BY MEANS AMDT